

# Oil Field Environmental Incident Summary

**Incident:** 20140502122859      **Date/Time of Notice:** 05/02/2014 12:28

**Responsible Party:** MARATHON OIL COMPANY

**Well Operator:** MARATHON OIL COMPANY

**Well Name:** LUCILLE USA 14-10H

**Field Name:** WOLF BAY

**Well File #:** 27155

**Date Incident:** 5/1/2014      **Time Incident:** 09:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 146

**Rng:** 92

**Sec:** 16

**Qtr:**

**Location Description:**

**Submitted By:** Ashley Schaper

**Received By:**

**Contact Person:** Ashley Schaper  
3172 HWY 22 N  
DICKINSON, ND 58601

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 3 Mile

**Distance Nearest Water Well:** 2 Mile

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	4	Gallons	4	Gallons	4	gallons

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/9/2015

**Clean Up Concluded:** 5/2/2014

**Risk Evaluation:**

No immediate risk

**Areal Extent:**

off location light mist of 61 x 85 feet

**Potential Environmental Impacts:**

No potential environmental impacts

**Action Taken or Planned:**

Crew was sent out to clean up the affected area

**Wastes Disposal Location:** Approved landfill

**Agencies Involved:**

**Updates**

---

**Date:** 5/4/2014      **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Spray off location due to unspecified cause. Followup is necessary.

---

**Date:** 5/29/2014      **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

The weather was 90 °F, clear, with wind from the south 30 mph. This is a site that appears to have had two new wells drilled recently, including the well in the spill report. I walked around the site and did not see any vegetation impacted by the misting. No further followup needed at this time.